


 MESSBEISPIELE FÜR DIE VARIO- UND UNIVERSAL TIEFEN MESSSCHIEBER
 MEASURING EXAMPLES FOR THE VARIO AND UNIVERSAL DEPTH GAUGES
 EXEMPLES DE MESURE POUR LES PIEDS A COULISSE VARIO ET UNIVERSAL
 ESEMPI D'IMPIEGO DEI CALIBRI DI PROFONDITA VARIO E UNIVERSAL

841120.500




 Nuten-Messtaster:
Antastflächen liegen genau auf gleicher Ebene

 Groove & slot measuring feeler: Measuring faces on the same plane

 Palpeur pour rainures: Les deux faces du palpeur se trouvent exactement au même plan

 Piedino per scanalature: Le due facce del tastatore sono sullo stesso piano

841120.600




Tiefen-Messtaster

Depth feeler

Palpeur pour profondeur

Piedino per profondità

841120.700




Messtaster für Querbohrungen:
Rubinkugel kann mit Preset-Taste kompensiert werden

Feeler for cross holes:
Diameter of ruby ball is compensated with Preset-Switch

Palpeur pour orifices transversaux: Le diamètre de bille en rubis est compensé avec la touche Preset

Piedino per forature trasversali: Sfera di rubino può essere compensata con il tasto Preset

841120.800




Universal-Halter:

Universal support:

Support universel:

Supporto universale:

18




 Beim Messen keine Rechenarbeit

 No calculations required to measure grooves and slots

 Aucun calcul pour la mesure de rainures et d'épaulements

 Nessun lavoro di calcolo nella misura




Messen auf Absätzen

Measuring steps

Palper des paliers

Misurare spallamenti




Ideal zum Messen von Querbohrungen

Ideal for measurements of cross holes

Idéale pour mesurer des orifices transversaux

Ideale per la misura di forature trasversali




für alle Norm-Messtaster ...

for all standard feelers ...

pour tous les palpeurs standard ...

per tutti i tastini normalizzati Filetto M 2,5




 Tasterstärke mit der PRESET-Taste kompensieren

 Thickness of feeler is compensated with PRESET-Switch

 La touche PRESET compense l'épaisseur du palpeur

 Compensare lo spessore del piedino con il tasto PRESET




Messen in Einstichen

Measuring undercuts

Mesurer des piqûres fines

Misurare scanalature




Präzise Antastung auch in grossen Tiefen

Precise locating in hard to reach areas

Permet de palper précisément en grandes profondeurs

Esplorazione precisa anche a grandi profondità



... und Spezialtaster

... and special feelers

... et palpeurs spéciales

... e piedini speciali